

LOCATION: BLM-26-404

HYDRAULIC CONDITIONS: Apparent confined, rhyolite bedrock

PERTINENT OBSERVATIONS: Drilled air-foam rotary from 60'-287' with no formation water observed (10/21/91). Drilled from 287'-437' on 10/22/91. Encountered tuff bedrock at 310', and rhyolite bedrock at 405'. Rhyolite bedrock made profuse water from \approx 408'-437'. Drilled from 437'-462'(TD) on 10/23/91 to assure room for completion.